





## USAGE

When changing the battery or attaching a new battery to the tool, make sure it is correctly attached. The batteries perform at their best around room temperature.

### **HANDLING AND FIRST AID MEASURES**

Batteries should always be handled with care, as they contain a lot of power and energy.







- Do not tamper with the batteies, try to open batteries, or touch the terminals
- Handle batteries with care to avoid dropping batteries on the ground or in other ways mechanically damage them
- Keep away from water or other liquids, heat sources such as fires etc at all times, and direct sunlight for extended periods of time
- · If a battery shows signs of damage, scrap and replace it

#### **SERVICE LIFE**

Keep in mind that the battery ages even when not used. To achieve the longest possible service life, Use battery in temperatures within 10 °C to 40 °C at all times.

## STORAGE

Avoid storing batteries fully charged. To maximize service life, it is optimal to store the batteries at 30-40 % stateof-charge in the temperature range from 0 °C to 25 °C.

Here are some more tips on how to store batteries to maximize service life:





-50 °C —

- Do not store your battery connected to the power tool for longer periods
- · Maintenance charge batteries in storage, preferably every 6 months
- Do not store batteries in a regular refrigerator, as the high humidity is bad for the batteries

# RECYCLING

batteries should never be thrown away in a normal waste bin. Discharge batteries completely before recycling, and secure the contacts, by e.g. using electrical tape, to avoid short-circuiting.



Committed to sustainable productivity

Atlas Copco